

Brass catcher for Walther GSP cal .32







For optimum results adjust the rotating head and make sure the lever weapons do not strike the "bridge" of the head.

Do not use excessive force force when tightening and manoeuvring.

This product is made in 3D printing.

Do not expose too long in the sun by strong heat.

- # 1: Insert the bracket into the base of the charger.
- # 2: Insert the magazine into the gun.
- # 3: Insert the net into the holder.

For disassembly, repeat these operations in reverse order (except # 1).

Note: The ejection of the casings is not regular, it is possible that the behavior of some is not optimal.